

External and Internal Works at Robert Browning School

Elevation works have begun at Robert Browning Primary School in SE17. The external refurbishment works will include the overhaul, repair and redecorations to a large number of timber windows and external doors as well as some repairs and redecorations to the SW elevation. Plus we will undertake brickwork repairs in order to sensitively restore this handsome traditional Victorian building. Further works also include the internal refurbishment and remodelling of the Staff and PPA rooms.